

## Curriculum Vitae of the machine Reference number: x 23509







## HORIZON VAC - 100 Collating and Stitching Line

## **SPECIAL OFFER**

Manufacturer:

Horizon International Inc.,

Kyoto, Japan

2009

Production Year:

Counter: 9 sheets

Availability:

immediately

Sale Reason:

closing company

بر

Condition of the Machine:

very good condition, well maintained, worn out according to its age still in production

The Condition of the Machine assessment presented in this CV was either obtained from the

Disclaimer:

last machine operator or is based on an inspection performed by our employee, just to provide you with as much information as possible. For more certainty we recommend your own check or an assessment of an independent mechanic. We cannot provide you with any machine guarantee.

More Details: