

## Curriculum Vitae of the machine Reference number: 23504



## KOLBUS DA 230 Lining machine

**Manufacturer:** Kolbus GmbH & Co KG,  
Rahden, Germany  
**Production Year:** 1991

**More Details:**  
performance 35 passes/minute  
failure rate: 1.10%  
from 2019 to the end of 2022, the machine produced almost 12,000,000 cycles.  
documentation: original German/English/Czech

**Availability:** immediately

**Work Experiences:** the machine is used on a daily basis during single-shift operation

**Sale Reason:** purchase of a new machine



**Condition of the Machine:** very good condition, well maintained, worn out according to its age can be seen running

**Disclaimer:** The Condition of the Machine assessment presented in this CV was either obtained from the last machine operator or is based on an inspection performed by our employee, just to provide you with as much information as possible. For more certainty we recommend your own check or an assessment of an independent mechanic. We cannot provide you with any machine guarantee.