

Curriculum Vitae of the machine Reference number: 13620



VIPTRONIC VIPCAM 118 S/P Densitometer

Production Year: about 2006

More Details:
plate densitometer

Availability: immediately

Sale Reason: closing company



Condition of the Machine: perfect condition, only shortly used machine can be seen running

Disclaimer: The Condition of the Machine assessment presented in this CV was either obtained from the last machine operator or is based on an inspection performed by our employee, just to provide you with as much information as possible. For more certainty we recommend your own check or an assessment of an independent mechanic. We cannot provide you with any machine guarantee.